IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

re Patent of

U.S. Patent No.

: 6,806,577 B2

Issued

: October 19, 2004

Title

: FILL PATTERN GENERATION FOR SPIN-ON GLASS AND

RELATED SELF-PLANARIZATION DEPOSITION

Docket No.

: MIO 0074 V2/40509.287/00-0854.02

Certificate of Corrections Branch

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

Sir:

CERTIFICATE OF MAILING

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on March 21, 2005.

for Cofe

REQUEST FOR CERTIFICATE OF CORRECTION FOR PTO MISTAKE UNDER 35 U.S.C. 254 and 37 C.F.R. 1.322

In the matter of U.S. Patent No. 6,806,577 B2, it is respectfully requested that a Certificate of Correction be issued to cover the following errors which occurred in the printing of the patent.

Col. 3, line 66, "reticle," should read --reticle--; Claim 15, Col. 14, line 2, "patters," should read --patterns,--; and Claim 15, Col. 14, line 9, "coplanar" should read --co-planar--.

REMARKS

It is respectfully requested that a Certificate of Correction be issued for the aboveidentified patent. All of the above errors occurred during the printing of the patent and, therefore, no fee is due. Two (2) copies of the required Certificate of Correction Form PTO/SB/44 are enclosed.

> Respectfully submitted, **DINSMORE & SHOHL LLP**

John D. Reed

Registration No. 46,506

One Dayton Centre One South Main St., Suite 1300 Dayton, Ohio 45402-2023 Telephone: (937) 449-6400 Facsimile: (937) 449-6405

JDR/vlh Encl.

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6,806,577 B2

DATED

: October 19, 2004

INVENTOR(S) : Juengling et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 3, line 66, "reticle," should read --reticle--;

Claim 15, Col. 14, line 2, "patters," should read --patterns,--; and

Claim 15, Col. 14, line 9, "coplanar" should read --co-planar--.

_	_									—	
n	м	ΔB	- ! N	162	ΔГ	שחו	200	S OF	- CEI	VIΠ	⊏ D∙
ш	vı.	\neg ı	_613		\neg L	<i>'</i>	ι ι ι ι	. OI	그ㄴ	NL)	LIX.

Dinsmore & Shohl LLP

One Dayton Centre

One South Main Street, Suite 1300

Dayton, Ohio 45402-2023

PATENT NO.___

6,806,577 B2

No. of additional copies

1 of 1

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.